

# Oil Field Environmental Incident Summary

**Incident:** 20150704120753      **Date/Time of Notice:** 07/04/2015 12:07  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** BULLRUSH 24-10H  
**Field Name:** ELIDAH      **Well File #:** 18380  
**Date Incident:** 7/3/2015      **Time Incident:** 22:30      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 151      **Rng:** 97      **Sec:** 10      **Qtr:** SW SE  
**Location Description:**

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile  
**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - On Facility Site      **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

approximately 80 feet by 100 feet. All of it was contained on the facility pad.

***Potential Environmental Impacts:***

None.

***Action Taken or Planned:***

the free liquid has been collected with a vacuum truck and sent for recovery. A crew will be sent out to collect the oil impacted gravel for appropriate disposal.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 7/6/2015     ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary this spill remained on location. NDIC retains oversight.